#SECAP

17TH ROAD SAFETY CONFERENCE



11 MARCH 2025



CASCAIS, PORTUGAL



HOSTED BY:



TESTING TRAFFIC CALMING EQUIPMENT TO IMPROVE SAFETY IN HIGHWAY WORK ZONES

Marco Pereira Infrastructure Intelligence Technician (Road Safety Unit) mapereira@ascendi.pt



Table of contents

01

Ascendi

Overview

04

Case Studies

02

Project

Framework

05

Findings

03

Selected

Equipment




Ascendi Overview


Ascendi is a reference organization in the road infrastructure market that manages infrastructure assets and provides toll collection and operation & maintenance services.

6 Highway concessions

10&M Contract

707 Km in operation





Project Framework

- Ascendi's 24-27 RSAP (Road Safety Action Plan)
- Safety in Work Zones
- Objective: Zero Work-Related Injuries
- Two main risk factors:
- > Speeding
- Driver's Distraction







The problem: Speeding in Workzones

	Costa de Prata	Norte Concession	
Measuring Point	(A29)	(A11)	
	04/11/2022	Location 1 11/11/2022	Location 2 11/11/2022
Speed Limit	80 km/h	80 km/h	80 km/h
Average speed (Vd)	76 km/h	69 km/h	69 km/h
Maximum Speed (Vmax)	154 km/h	110 km/h	106 km/h
V85 (85th percentile)	87 km/h	85 km/h	86 km/h
Non-Compliance (%)	31 %	23%	23%

- Speed monintoring in 3 road closure locations during road pavement works
- Results displayed high values of Non-Compliance with the speed limit (%)



O3 Selected Equipment

Dynamic Speed Sign (DSS)

How it works:

- Registers and dynamically displays the speed of approaching vehicles.
- The displayed speed updates every 2-3 seconds as a vehicle approaches, allowing the driver to see the speed variation.
- The speed is shown in green when below the speed limit and in red when above it.

Objective: Reduction of practised speeds

Tested: May/June 2023 on Kilometre 1 of the A25



Temporary Rumble Strips (TRS)

How it works:


Designed to alert drivers through audible and vibratory
 feedback when their vehicle approaches the closed lane due to the work zone.

Equipment: ROADQUAKE 2F by PSS

- Designed for speeds up to 130 km/h
- Approximate weight of 50 Kg

Objective: Improve driver awareness

Tested: October 2023 on Kilometre 20 of the A7







O4 Case Studies

Project Scope

- Project Partners:
- a) IMT (Institute for Mobility and Transport)
- **b) GNR** (Republican National Guard)
- c) ANSR (Road Safety National Authority)
- The tested equipment was included in the Lane Closure
- Need to Adapt the Temporary Signalling
 Scheme of the work zone to consider the equipment











Location: Highway A25, Kilometre 100

Date: January 2024

Road Work: Reinforcement of an excavation slope

Road Constraints: Right Lane Closure

Equipment Used: DSS + TRS

Objective: Speed Monitoring With and Without the

DSS/TRS

Test Approved by the Concession authority in

September 2023.





Scenarios:

- Scenario 1 No additional equipment used
- Scenario 2 DSS
- Scenario 3 TRS

Results:

	Scenario 1	Scenario 2 (S2)	Scenario 3 (S3)
1st Case Study	NO ADDITIONAL EQUIPMENT	<u>WITH</u> THE DYNAMIC PANEL	WITH THE TEMPORARY RUMBLE STRIPS
Measuring Period	29/01/2024 10:40h - 30/01/2024 10:50h	30/01/2024 10:50h - 31/01/2024 11:00h	31/01/2024 11:00h - 01/02/2024 11:00h
Speed Limit (km/h)	80	80	80
Measured Vehicles Average Speed (Vd) V85 (85th percentile) (km/h)	9974	8038	7983
	89	80 (-10%)	82 (-8%)
	101	94 (-7%)	95 (-6%)
Non-Compliance (%)	77	50 (-27pp)	56 (-21pp)

- With the installation of the DSS (Scenario 2) and the TRS (Scenario 3):
 - ➤ The percentage of non-compliances fell significantly;
 - ▶ Both the V85 speed and average speed, presented satisfactory reductions on both scenarios;
 - ➤ A gradual small displacement of the TRS was verified during the measurement period

Date: October 2023, Night Period

Location: Highway A7, Kilometre 20

Road Work: Major Pavement Repairs

Road Constraints: Left Lane Closure

Equipment Used: Dynamic Speed Panel and/or Rumble

Strips

Objective: Speed Monitoring With and Without the

Panel/Rumble Strips



Scenarios:

- Scenario 1 No additional equipment used
- Scenario 2 DSS
- Scenario 3 TRS
- Scenario 4 TRS + DSS

Results:

		Scenario 1	Scenario 2	Scenario 3	Scenario 4
/	2nd Case Study	NO ADDITIONAL EQUIPMENT	WITH THE DYNAMIC PANEL	WITH THE TEMPORARY RUMBLE STRIPS	WITH THE TEMPORARY RUMBLE STRIPS AND THE DYNAMIC PANEL
	Measuring Period	13/10/2023 02:00h - 03:00h	13/10/2023 01:00h - 02:00h	13/10/2023 00:00h - 01:00h	12/10/2023 23:00h - 00:00h
	Speed Limit (km/h)	80	80	80	80
	Measured Vehicles	46	47	73	155
	Average Speed (Vd)	75	67 (-11%)	69 (-8%)	69 (-8%)
	V85 (85th percentile) (km/h)	85	80 (-6%)	82 (-4%)	80 (-6%)
	Non-Compliance (%)	41	19 (-22pp)	21 (-20pp)	15 (-26pp)

In the 3 scenarios where an equipment was used:

- > The percentage of non-compliances fell significantly;
- > Satisfactory reduction in the average speed;
- The **results** were very **similar** to the tests conducted in the **daytime** period.
- ➤ Despite the reduced sample size, it was possible to notice an **earlier vehicle transition to the available** lane during the lane closure.



05 Findings

Findings

- ➤ Both Case Studies showed significant and constant speed reduction improvements that are likely to be related with the use of DSS and TRS:
- V85: -6% Average
- Average Speed: -9% Average
- ➤ It was possible to identify an increase to the number of vehicles that transitioned to the available lane at a distance of 300m to the constraint (+ 4%), when the Temporary Rumble Strips were used.
- > The project has showed promising results, justifying an extension of its end date to June 2026.

ASECAP ...